



Lodging Establishment Inspection Report

Establishment Information	
Facility Name PRAIRIE INN & SUITES	Facility Type Lodging 31-99 Rooms (LH2)
Facility ID # HSAT-7QWFRL	Facility Telephone # 608 878-4490
Facility Address 3913 CIRCLE DR HOLMEN , WI 54636 -9187	
Licensee Name PRAIRIE INN & SUITES INC	Licensee Address W5716 STUMILIN RD HOLMEN , WI 54636

Inspection Information		
Inspection Type Routine	Inspection Date 11/09/2016	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.


Observed Violations
<p>Total # 1</p> <p>Room: Laundry room - adjacent sleeping room and hall are missing CO detectors.</p> <p>Observed Violations - 46 - Smoke and Carbon Monoxide Detection</p> <p>OBSERVATION: Carbon monoxide detector absent where Fuel Burning Appliances are present [identify type and specific location of FBA]</p> <p>CORRECTIVE ACTION(S): Provide carbon monoxide detectors in all required locations. Correct By: 09-Nov-2016</p> <p>CODE CITATION: ATCP 72.145 (3) INSTALLATION REQUIREMENTS.</p> <p>The operator shall install carbon monoxide detectors in compliance with the requirements of s. 101.149 (2), stats., and s. SPS 321.097 or 362.1200, as follows: (a) Except as provided in par. (b) or in sub. (6) of this section, the operator shall install a carbon monoxide detector in each residential building in all of the following places not later than the date specified under par. (c):</p> <ol style="list-style-type: none"> 1. In the basement of the building if the basement has a fuel-burning appliance. 2. Within 15 feet of each sleeping area of a unit that has a fuel-burning appliance. 3. Within 15 feet of each sleeping area of a unit that is immediately adjacent to a unit, located on the same floor level that has a fuel-burning appliance. 4. In each room that has a fuel-burning appliance and that is not used as a sleeping area, not more than 75 ft from the fuel burning appliance. 5. In each hallway leading from a unit that has a fuel-burning appliance, in a location that is within 75 ft from the unit measure from the door of the unit along the hallway leading from the unit, except that, if there is no electrical outlet within this distance, the operator shall place the carbon monoxide detector at the closest available electrical outlet in the hallway. <p>(b) If a unit is not part of a multiunit building, the operator need not install more than one carbon monoxide detector in the unit.</p> <p>(c) 1. Except as provided under subd. 2., the operator shall comply with the requirements of this subsection before a residential building is occupied.</p> <p>2. The operator shall comply with the requirements of this subsection not later than April 1, 2010, if construction of the residential building was initiated before October 1, 2008, or if the department of safety and professional services approved the plans for the construction of the building under s. 101.12, Stats., before October 1, 2008.</p>

Comments

Rooms 112, 125 and 206 inspected.
Discussed pest control and smoke detection. The building has a fire alarm and smoke detection system and stand alone smoke detectors. 206 is missing the stand alone smoke detector.

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge



Tammy mccooy

Sanitarian



Doug Schaefer
(608) 785-9679