



Recreational Water Establishment Inspection Report

Establishment Information	
Facility Name AMERICINN OF WEST SALEM	Facility Type Indoor Pool
Facility ID # ASTS-9AAK5N	Facility Telephone # 608 786-3340
Facility Address 125 BUOL RD WEST SALEM , WI 54669	
Licensee Name TROUT CREEK 1 LLC	Licensee Address 12554 STATE HWY 131 SOLDIERS GROVE , WI 54655

Pool Parameters	
Free Available Chlorine/Bromine	2.0
Combined Chlorine	0.6
pH	7.6
Alkalinity	100
Cyanuric Acid	-
Temperature	86
Flowmeter Reading(s)	60
Pressure Gauges Reading(s)	18

Inspection Information		
Inspection Type Routine	Inspection Date January 26, 2017	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 1</p> <p>Observed Violations - 21 - Plumbing air-gaps, cross-connections, maintained, installed piping coded or labeled</p> <p>OBSERVATION: (CORRECTED DURING INSPECTION): The hose bibb by the drinking fountain on the pool deck is not protected against backsiphonage.</p> <p>CORRECTIVE ACTION(S): Install a hose bibb atmospheric vacuum breaker that meets the ASSE 1011 standard on the hose bibb. Correct By: 26-Jan-2017</p> <p>CODE CITATION: ATCP 76.33 Facility maintenance, repair and sanitation. (1) POOL AREA. (d) Hosing. Hosing shall be provided in adequate lengths to flush the entire pool deck. All hose bibbs shall be protected against backsiphonage by the proper installation of an approved backflow prevention device as required under s. SPS 390.16 (4)</p>

Comments
<p>Contact Sam (785-9732) with questions. Signed Virginia Graeme Baker PSSA approval letter is on hand. Pool drain grate lifespan is 10 years (installed 2010).</p>

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian

Steve Plenge

Samuel Welch
(608) 785-9732



Recreational Water Establishment Inspection Report

Establishment Information	
Facility Name AMERICINN OF WEST SALEM	Facility Type Additional Indoor Pool
Facility ID # ASTS-9AAK6D	Facility Telephone # 608 786-3340
Facility Address 125 BUOL RD WEST SALEM , WI 54669	
Licensee Name TROUT CREEK 1 LLC	Licensee Address 12554 STATE HWY 131 SOLDIERS GROVE , WI 54655

Pool Parameters	
Free Available Chlorine/Bromine	1.6
Combined Chlorine	1.4
pH	7.4
Alkalinity	40
Cyanuric Acid	-
Temperature	102
Flowmeter Reading(s)	-
Pressure Gauges Reading(s)	21

Inspection Information		
Inspection Type Routine	Inspection Date January 26, 2017	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 2</p> <p>Observed Violations - 16 - pH alkalinity within limits or balanced, Cyanuric acid - within limits, Superoxidation - done as needed.</p> <p>OBSERVATION: The total alkalinity is 40 ppm.</p> <p>CORRECTIVE ACTION(S): Maintain the total alkalinity between 60 and 180 ppm. Correct By: 26-Jan-2017</p> <p>CODE CITATION: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (d) Alkalinity. The total alkalinity of pool water shall be maintained between 60 and 180 ppm as calcium carbonate unless it can be shown that another level of total alkalinity produces chemically balanced water based on calculations approved by the department.</p> <p>Observed Violations - 14 - Disinfectant / feeders - proper concentration and chemical used. Gas chlorine.</p> <p>OBSERVATION: The chlorine residual was 1.6 ppm at the time of the inspection.</p> <p>CORRECTIVE ACTION(S): Close the pool and raise the chlorine residual to 3.0 before re-opening. Correct By: 26-Jan-2017</p> <p>CODE CITATION: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (a) Minimum disinfectant residuals. Except as provided in par. (b), feeding shall result in the minimum disinfectant residuals in Table ATCP 76.14.</p>

Comments

Close whirl until chlorine is 3.0 - 10.0 ppm and alkalinity is 60-180 ppm. Lower whirl combined chlorine to \leq 0.8 ppm. Adjust flowmeter to float freely. Contact Sam (785-9732) with questions. Signed Virginia Graeme Baker PSSA approval letter is on hand. Pool drain grate lifespan is 10 years (installed 2010).

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge



Steve Plenge

Sanitarian



Samuel Welch
(608) 785-9732