



Recreational Water Establishment Inspection Report

Establishment Information	
Facility Name RADISSON LA CROSSE HOTEL	Facility Type Indoor Pool
Facility ID # HSAT-7QWGY2	Facility Telephone #
Facility Address 200 HARBORVIEW PLAZA LA CROSSE, WI 54601	
Licensee Name R L H CORP	Licensee Address 200 HARBORVIEW PLAZA LA CROSSE, WI 54601

Pool Parameters	
Free Available Chlorine/Bromine	5.2
Combined Chlorine	0.4
pH	7.2
Alkalinity	70
Cyanuric Acid	
Temperature	91
Flowmeter Reading(s)	85
Pressure Gauges Reading(s)	24

Inspection Information		
Inspection Type Routine	Inspection Date December 05, 2016	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 3</p> <p>Observed Violations - 11 - Chemicals - proper labeling and storage, no mixing of chemicals, smoking prohibited OBSERVATION: Material safety data sheets are not available for all chemicals used in the facility. Missing MSDS includes: Alkalinity Plus, pH rise, SwimShock. CORRECTIVE ACTION(S): Provide material safety data sheets for all chemicals used in the facility. Correct By: 05-Dec-2016 CODE CITATION: ATCP 76.12 Labeling, storing, mixing, and handling chemicals. (4) HANDLING. (b) Material safety data sheet. Material safety data sheets shall be readily available at the pool attraction</p>

area for every chemical used.

Observed Violations - 30 - Toilet, shower, dressing rooms, provided as needed, clean maintained, hand drying, toilet tissue, suits, caps, or towels provided to patrons - clean, thoroughly laundered, storage

OBSERVATION: The soap dispenser in shower is empty.

CORRECTIVE ACTION(S): Provide soap at all hand washing sinks and showers. Correct By: 07-Dec-2016

CODE CITATION: ATCP 76.33 Facility maintenance, repair and sanitation. (2) SHOWER, TOILET AND DRESSING FACILITIES. (e) Soap shall be continually provided at each hand washing sink and shower in permanently installed dispensing devices. The dispensers shall be maintained in operating condition.

Observed Violations - 05 - Water level maintained, Proportional flow - gutter or skimmers versus drain

OBSERVATION: The skimmer to main drain flow ration is not set correctly.

CORRECTIVE ACTION(S): Readjust the flow so that only 20% comes through the main drain and 80% comes through the skimmers. Correct By: 05-Dec-2016

CODE CITATION: ATCP 76.11 Recirculation system. (2) SKIMMERS AND RECIRCULATION FLOW.

(a) The flow through each skimmer shall be adjusted as often as necessary to maintain a vigorous skimming action at each skimmer. The pool water level shall be maintained at an elevation so that continuous effective surface skimming is accomplished through skimmers or over the gutter lip. For gutter pools, approximately 75% of the required recirculation flow shall be through the gutter and 25% through the main drain during normal operation. For pools with skimmers, approximately 80% of the recirculation flow shall be through skimmers and 20% through the main drain. For reverse flow pools, 100% of the required circulation shall be through the gutter or skimmer.

Comments

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian

**Nicole Frankfourth
(608) 785-9731**



Recreational Water Establishment Inspection Report

Establishment Information	
Facility Name RADISSON LA CROSSE HOTEL	Facility Type Additional Indoor Pool
Facility ID # HSAT-7QXK4E	Facility Telephone #
Facility Address 200 HARBORVIEW PLAZA LA CROSSE, WI 54601	
Licensee Name R L H CORP	Licensee Address 200 HARBORVIEW PLAZA LA CROSSE, WI 54601

Pool Parameters	
Free Available Chlorine/Bromine	1.6
Combined Chlorine	0.8
pH	7.4
Alkalinity	30
Cyanuric Acid	
Temperature	106.2
Flowmeter Reading(s)	20? (flowmeter may be broken)
Pressure Gauges Reading(s)	16

Inspection Information		
Inspection Type Routine	Inspection Date December 05, 2016	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 5</p> <p>Observed Violations - 08 - Recirculation rate-turnover OBSERVATION: The whirlpool has a maximum turnover rate of greater than 30 minutes with flowmeter at 20 gpm. CORRECTIVE ACTION(S): Immediately adjust or repair the equipment to operate at a proper turnover rate. Correct By: 05-Dec-2016 CODE CITATION: ATCP 76.11 Recirculation system. (4) PUMPS. The pump manufacturer's maintenance and operating instructions shall be followed. Recirculation pumps shall continuously achieve the designed pool water recirculation rate except during maintenance operations. The turnover</p>

time for pools shall be as follows: (d) Whirlpools. The maximum turnover time for a whirlpool shall be 30 minutes.

Observed Violations - 09 - Gauges and flowmeters maintained, operated, accurate, installed, approved pressure or vacuum

OBSERVATION: The flowmeter on spa (whirlpool) is not functional.

CORRECTIVE ACTION(S): Repair or replace the specified equipment so an accurate reading can be recorded. Correct By: 12-Dec-2016

CODE CITATION: ATCP 76.11 Recirculation system. (5) FLOWMETERS, VALVES, AND GAUGES. Flowmeters, valves and gauges shall be maintained in operating condition.

Observed Violations - 16 - pH alkalinity within limits or balanced, Cyanuric acid - within limits, Superoxidation - done as needed.

OBSERVATION: The total alkalinity is 30 ppm.

CORRECTIVE ACTION(S): Maintain the total alkalinity between 60 and 180 ppm. Correct By: 05-Dec-2016

CODE CITATION: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (d) Alkalinity. The total alkalinity of pool water shall be maintained between 60 and 180 ppm as calcium carbonate unless it can be shown that another level of total alkalinity produces chemically balanced water based on calculations approved by the department.

Observed Violations - 22 - Water temperature - within limits, Accurate thermometers

OBSERVATION: The temperature of the whirlpool water is 106.2 degrees Fahrenheit.

CORRECTIVE ACTION(S): Adjust the temperature to bring it within permissible limits pursuant to ATCP 76.19(4)(c). Correct By: 05-Dec-2016

CODE CITATION: ATCP 76.19 Water supply and temperature. (4) WATER TEMPERATURE. (c) The water temperature in whirlpools may not exceed 104°F. (40°C.)

Observed Violations - 05 - Water level maintained, Proportional flow - gutter or skimmers versus drain

OBSERVATION: The skimmer to main drain flow ration is not set correctly. One set 100% open, one is set 80% open.

CORRECTIVE ACTION(S): Readjust the flow so that only 20% comes through the main drain and 80% comes through the skimmers. Correct By: 05-Dec-2016

CODE CITATION: ATCP 76.11 Recirculation system. (2) SKIMMERS AND RECIRCULATION FLOW. (a) The flow through each skimmer shall be adjusted as often as necessary to maintain a vigorous skimming action at each skimmer. The pool water level shall be maintained at an elevation so that continuous effective surface skimming is accomplished through skimmers or over the gutter lip. For gutter pools, approximately 75% of the required recirculation flow shall be through the gutter and 25% through the main drain during normal operation. For pools with skimmers, approximately 80% of the recirculation flow shall be through skimmers and 20% through the main drain. For reverse flow pools, 100% of the required circulation shall be through the gutter or skimmer.

Comments

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department. A re-inspection to assess your correction of these violations will be conducted on, or about, December 07, 2016

Person in Charge

Sanitarian

Nicole Frankfourth
(608) 785-9731



Recreational Water Establishment Inspection Report

Establishment Information	
Facility Name RADISSON LA CROSSE HOTEL	Facility Type Additional Indoor Pool
Facility ID # HSAT-7QXK4E	Facility Telephone #
Facility Address 200 HARBORVIEW PLAZA LA CROSSE, WI 54601	
Licensee Name R L H CORP	Licensee Address 200 HARBORVIEW PLAZA LA CROSSE, WI 54601

Pool Parameters	
Free Available Chlorine/Bromine	
Combined Chlorine	
pH	
Alkalinity	20
Cyanuric Acid	
Temperature	104
Flowmeter Reading(s)	45
Pressure Gauges Reading(s)	

Inspection Information		
Inspection Type Follow Up	Inspection Date December 20, 2016	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 1</p> <p>Observed Violations - 16 - pH alkalinity within limits or balanced, Cyanuric acid - within limits, Superoxidation - done as needed. REPEAT OBSERVATION: The total alkalinity is 20 ppm. CORRECTIVE ACTION(S): Maintain the total alkalinity between 60 and 180 ppm. Correct By: 05-Dec-2016 CODE CITATION: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (d) Alkalinity. The total alkalinity of pool water shall be maintained between 60 and 180 ppm as calcium carbonate unless it can be shown that another level of total alkalinity produces</p>

chemically balanced water based on calculations approved by the department.

Corrected Hazards

The following hazard(s) have been corrected since the last inspection.

Total # 4

ATCP 76.11(4)(d) - RECIRCULATION RATE NOT MET - WHIRLPOOLS

OBSERVATION: The whirlpool has a maximum turnover rate of greater than 30 minutes with flowmeter at 20 gpm.

CORRECTIVE ACTION(S): Immediately adjust or repair the equipment to operate at a proper turnover rate. Correct By: 05-Dec-2016

CODE CITATION: ATCP 76.11 Recirculation system. (4) PUMPS. The pump manufacturer's maintenance and operating instructions shall be followed. Recirculation pumps shall continuously achieve the designed pool water recirculation rate except during maintenance operations. The turnover time for pools shall be as follows: (d) Whirlpools. The maximum turnover time for a whirlpool shall be 30 minutes.

ATCP 76.11(5) - FLOWMETER, VALVES AND GAUGES NOT FUNCTIONAL

OBSERVATION: The flowmeter on spa (whirlpool) is not functional.

CORRECTIVE ACTION(S): Repair or replace the specified equipment so an accurate reading can be recorded. Correct By: 12-Dec-2016

CODE CITATION: ATCP 76.11 Recirculation system. (5) FLOWMETERS, VALVES, AND GAUGES. Flowmeters, valves and gauges shall be maintained in operating condition.

[A] ATCP 76.11(2)(a) - SKIMMER/MAIN DRAIN RATIO INCORRECT

OBSERVATION: The skimmer to main drain flow ration is not set correctly. One set 100% open, one is set 80% open.

CORRECTIVE ACTION(S): Readjust the flow so that only 20% comes through the main drain and 80% comes through the skimmers. Correct By: 05-Dec-2016

CODE CITATION: ATCP 76.11 Recirculation system. (2) SKIMMERS AND RECIRCULATION FLOW. (a) The flow through each skimmer shall be adjusted as often as necessary to maintain a vigorous skimming action at each skimmer. The pool water level shall be maintained at an elevation so that continuous effective surface skimming is accomplished through skimmers or over the gutter lip. For gutter pools, approximately 75% of the required recirculation flow shall be through the gutter and 25% through the main drain during normal operation. For pools with skimmers, approximately 80% of the recirculation flow shall be through skimmers and 20% through the main drain. For reverse flow pools, 100% of the required circulation shall be through the gutter or skimmer.

ATCP 76.19(4)(c) - WHIRLPOOL WATER TEMPERATURE

OBSERVATION: The temperature of the whirlpool water is 106.2 degrees Fahrenheit.

CORRECTIVE ACTION(S): Adjust the temperature to bring it within permissible limits pursuant to ATCP 76.19(4)(c). Correct By: 05-Dec-2016

CODE CITATION: ATCP 76.19 Water supply and temperature. (4) WATER TEMPERATURE. (c) The water temperature in whirlpools may not exceed 104°F. (40°C.)

Comments

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian

James M. [unclear]

Nicole Frankfourth

Nicole Frankfourth
(608) 785-9731