



Recreational Water Establishment Inspection Report

<b>Establishment Information</b>	
Facility Name <b>ST VALLERIES APTS</b>	Facility Type <b>Outdoor Pool</b>
Facility ID # <b>HSAT-7QX2DJ</b>	Facility Telephone # <b>608 788-4306</b>
Facility Address <b>4445 MORMON COULEE RD LA CROSSE , WI 54601</b>	
Licensee Name <b>PARAMARK CORP</b>	Licensee Address <b>PO BOX 249 ROCHESTER , MN 55903 -0249</b>

<b>Pool Parameters</b>	
Free Available Chlorine/Bromine	1.2
Combined Chlorine	.2
pH	7.6
Alkalinity	160
Cyanuric Acid	0
Temperature	83.1
Flowmeter Reading(s)	60
Pressure Gauges Reading(s)	30

<b>Inspection Information</b>		
Inspection Type <b>Routine</b>	Inspection Date <b>06/08/2016</b>	Total Time Spent

**OPERATOR** - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

<b>Observed Violations</b>
<p><b>Total # 2</b></p> <p><b>Observed Violations - 30 - Toilet, shower, dressing rooms, provided as needed, clean maintained, hand drying, toilet tissue, suits, caps, or towels provided to patrons - clean, thoroughly laundered, storage</b></p> <p><b>OBSERVATION:</b> No hose bibb is conveniently located to adequately rinse the pool deck floor.</p> <p><b>CORRECTIVE ACTION(S):</b> Install a hose bibb in chemical room making it accessible to rinse and sanitize the floors. Correct By: 08-Jun-2016</p> <p><b>CODE CITATION:</b> DHS 172.33 Facility maintenance, repair and sanitation. (2) SHOWER, TOILET AND DRESSING FACILITIES. (i) Hose bibbs shall be conveniently located to adequately rinse and sanitize floors in shower, dressing, and toilet facilities.</p> <p><b>Observed Violations - 04 - Skimmers, gutters, drains, water inlets - number, clean, good repair, installed, operated</b></p> <p>This is a Critical violation</p> <p><b>OBSERVATION:</b> Submerged skimmer intake covers are not securely seated on the pool wall.</p> <p><b>CORRECTIVE ACTION(S):</b> Secure intake covers so they are not easily removed to comply with VGBA standards.</p> <p><b>CODE CITATION:</b> DHS 172.11 Recirculation system. (2) (b) Skimmers, skimmer weirs, and overflow gutters and drains shall be maintained so that they are clean and shall be repaired or replaced as needed. Skimmer covers shall be securely seated on deck.</p>

**Comments**

Call Aron Newberry, 785-9730 after the submerged intake covers have been replaced to comply with the VGBA standards.

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

A re-inspection to assess your correction of these violations will be conducted on, or about,

Person in Charge



**marilyn johnson**

Sanitarian

**Aron Newberry  
(608) 785-9730**



Recreational Water Establishment Inspection Report

<b>Establishment Information</b>	
Facility Name <b>ST VALLERIES APTS</b>	Facility Type <b>Outdoor Pool</b>
Facility ID # <b>HSAT-7QX2DJ</b>	Facility Telephone # <b>608 788-4306</b>
Facility Address <b>4445 MORMON COULEE RD LA CROSSE , WI 54601</b>	
Licensee Name <b>PARAMARK CORP</b>	Licensee Address <b>PO BOX 249 ROCHESTER , MN 55903 -0249</b>

<b>Pool Parameters</b>	
Free Available Chlorine/Bromine	9
Combined Chlorine	0
pH	7.2
Alkalinity	
Cyanuric Acid	
Temperature	85.1
Flowmeter Reading(s)	
Pressure Gauges Reading(s)	

<b>Inspection Information</b>		
Inspection Type Follow Up	Inspection Date 06/15/2016	Total Time Spent

**OPERATOR** - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

<b>Observed Violations</b>
<p><b>Total # 1</b></p> <p><b>Observed Violations - 30 - Toilet, shower, dressing rooms, provided as needed, clean maintained, hand drying, toilet tissue, suits, caps, or towels provided to patrons - clean, thoroughly laundered, storage</b></p> <p><b>REPEAT OBSERVATION:</b> No hose bibb is conveniently located to adequately rinse the pool deck floor.</p> <p><b>CORRECTIVE ACTION(S):</b> Install a hose bibb in chemical room making it accessible to rinse and sanitize the floors. Correct By: 08-Jun-2016</p> <p><b>CODE CITATION:</b> DHS 172.33 Facility maintenance, repair and sanitation. (2) SHOWER, TOILET AND DRESSING FACILITIES. (i) Hose bibbs shall be conveniently located to adequately rinse and sanitize floors in shower, dressing, and toilet facilities.</p>

<b>Comments</b>

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian

A handwritten signature in black ink, appearing to read 'Aron Newberry', with a stylized flourish at the end.

**Aron Newberry**  
**(608) 785-9730**