No. 146

21506312000

U. S. PUBLIC LAND SURVEY MONUMENT RECORD

SECTION 32 T 15 N, R 6 W, TOWN OF GREENFIELD

LA CROSSE COUNTY



LOCATION OF LANDMARK

CREW: WILLIAM C. JUNG
PETER F. FOLLANSBEE
DATE: 1/11/2006

WISCONSIN COORDINATE SYSTEM
North
East
Theta Angle
Horiz. Order
Vert. Order
TYPE OF LANDMARK
3/4" IRON BAR INSIDE AN IRON PIPE.
BEARINGS ARE REFERENCED TO

Describe any record evidence, monument evidence, testimonial evidence or any other material evidence you considered and whether the monument was found or restored through acceptance of an obliterated evidence location.

Rob Lampman set an iron pipe at this corner in 1978. This pipe has since been used as the corner in subsequent surveys. I accepted this pipe as the corner by "common report".

Describe or show any material discrepancy between the location of the restored corner and that of the corner previously restored or reestablished.

NONE KNOWN.

RECORD OF DURABLE WITNESS MONUMENTS

NO	DESCRIPTION	MAGNETIC BEARING	DISTANCE
1	SET A NAIL IN N.-SIDE OF A 5" HICKORY	WEST	18.03 FT.
2	SET A NAIL IN N.W.-SIDE OF A 13-1/2" OAK	N 50° E	23.92 FT.
3	SET A NAIL IN N.E.-SIDE OF A 5-1/2" HICKORY	S 82° E	15.79 FT.
4	SET A NAIL IN N.W.-SIDE OF AN 18" WHITE OAK	S 34° W	43.50 FT.

(NOT TO SCALE)



PLAN VIEW DRAWING OF REFERENCE TIES

MAP SHOWING DISTANCE AND DIRECTION TO OTHER PUBLIC LAND SURVEY CORNERS USED FOR REESTABLISHING THE CORNER

I made no further section measurements at this time. I reviewed the measurements made in other surveys.

I, WILLIAM C. JUNG, COUNTY SURVEYOR
HEREBY CERTIFY THAT THE CORNER LOCATION SHOWN ON THIS RECORD WAS DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT THIS U. S. PUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

William C. Jung — 1/16/06
Signature — Date

WISCONSIN
WILLIAM C. JUNG
S-1323
ONALASKA, WIS.
LAND SURVEYOR

Seal