



## Recreational Water Establishment Inspection Report

<b>Establishment Information</b>	
Facility Name HAMPTON INN & SUITES	Facility Type Indoor Pool
Facility ID # ASTS-A2KQ9A	Facility Telephone # 608
Facility Address 511 N 3RD ST LA CROSSE, WI 54601	
Licensee Name LA CROSSE HOTEL GROUP LLC	Licensee Address 511 N 3RS ST LA CROSSE, WI 54601

<b>Pool Parameters</b>	
Free Available Chlorine/Bromine	3.0
Combined Chlorine	0.6
pH	7.4
Alkalinity	90
Cyanuric Acid	
Temperature	89
Flowmeter Reading(s)	65
Pressure Gauges Reading(s)	17

<b>Inspection Information</b>		
Inspection Type Routine	Inspection Date January 04, 2017	Total Time Spent

**OPERATOR** - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

<b>Observed Violations</b>
<p><b>Total # 2</b></p> <p><b>Observed Violations - 11 - Chemicals - proper labeling and storage, no mixing of chemicals, smoking prohibited</b>  <b>OBSERVATION:</b> Material safety data sheets are not available for all chemicals used in the facility.  <b>CORRECTIVE ACTION(S):</b> Provide material safety data sheets for all chemicals used in the facility.            Correct By: 18-Jan-2017  <b>CODE CITATION:</b> ATCP 76.12 Labeling, storing, mixing, and handling chemicals. (4) HANDLING. (b) Material safety data sheet. Material safety data sheets shall be readily available at the pool attraction area for every chemical used.</p>

**Observed Violations - 26 - Permissible patron load, Rescue equipment, first aid equipment, telephone present, located, good condition, phone numbers posted**

**OBSERVATION:** A rope on the ring buoy is missing from the facility.

**CORRECTIVE ACTION(S):** Provide a rope 1.5x the maximum width of the pool for the facility and mount it in a conspicuous location. Correct By: 18-Jan-2017

**CODE CITATION:** ATCP 76.26 Rescue equipment. (1) REQUIRED EQUIPMENT. (b) For each basin of water over 4 feet in length and over 2 feet deep, a shepard's crook-type pole shall be provided. In addition, for each lifeguard chair, or for a pool 30 feet or more in width that does not have lifeguard chairs, at least one of the following shall be provided:

1. A ring buoy having a minimum outside diameter of 20 inches. Each ring buoy shall be attached to a 1/4 inch rope having a length not less than 1 1/2 times the maximum width of the pool or 50 feet, whichever is less.
2. A rescue tube.


**Comments**

1. [Lawson Aquatics main drain cover installed 12/11/15 - MLDFG1836](#)
2. [Reviewed logs from past year - have only been open 1 year.](#)
3. [Discussed DII reporting requirements - no incidents in past year.](#)

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian



**Nicole Frankfourth**  
**(608) 785-9731**